



City of Hermosa Beach

BUILDING INSPECTION LOG

THURS. 11/14/2024

F=Framing *E*=Electrical *P*=Plumbing *M*=Mechanical *I*=Insulation *D*=Drywall *SW*=Sheer Walls

EL=Exterior Lath *SP/SL*=Shower Pan/Lath *RS/RF*=Roof Sheathing/Final *BF*=Building Final

FRANK (310) 318-0258

	AM	PM	Inspection Window	ADDRESS	TYPE OF INSPECTION
1	X		9 to 12	802 the Strand	Final
2	X		9 to 12	107 Manhattan	PV Final
3	X		9 to 12	1620 Raymond	Final Plumbing
4	X		9 to 12	1212 19th. St.	TPP
5	X		9 to 12	2451 Silverstrand	TPP
6		X	1 to 4	210 PCH	Foundation
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					
24					
25					

JOSE (310) 318-0250

	AM	PM	Inspection Window	ADDRESS	TYPE OF INSPECTION
26	X		9 to 12	649 2nd st	Shear walls
27	X		9 to 12	77 15th st	E/F
28	X		9 to 12	352 33rd st	Electrical service panel
29	X		9 to 12	2425 Silverstrand	Drywall
30	X		9 to 12	520 24th	RS
31	X		9 to 12	2850 El Oeste	Foundation
32	X		9 to 12	1600 Ardmore #228	Plumbing
33	X		9 to 12	1407 Bonnie Brae	Shower lath
34		X	1 to 3	920 14th st	Exterior lath
35		X	1 to 3	1803 PCH	Insulation
36					
37					
38					
39					
40					